



A=09 4,0 x 40mm	B=31 3,0 x 12mm	C=51 3,5 x 30mm	D=01 	E=37 8,0 x 30mm
F=22 	G=30 6,0 x 10mm	H=08 	I=05 IL IR	J=01

1




E=03 8,0 x 30mm	I=04 IL	D=01 	G=12 6,0 x 10mm
-------------------------------	-----------------------	-----------------	-------------------------------


2



3



4





E=08



8,0 x 30mm

D=01



5


D=01




C=02



3,5 x 30mm




6



D=01




C=02




4,0 x 25mm



7



8



9

2X**A=02**



4,0 x 40mm

C=16



3,5 x 30mm

E=08

8,0 x 30mm

D=01**H=02****E x02**

10

3X**A=06**



4,0 x 40mm

C=24


3,5 x 30mm

E=12

8,0 x 30mm

D=01**H=06****E x02**

11



2X

IR

IL

B

B

B

B=30




3,0 x 12mm

I=05

IR

IL



3X

IR



IL

B

B

B

12



20.05.2021 - Rev. 1